



Bez důkladného prečtenia a pochopenia návodu k použitiu nepoužívajte tento výrobok.  
Reading and understanding instruction for use are required to use this product!



2 roky záruka  
2 years guarantee

#### Instructions for use, maintenance and storage the gloves GRIPPY (EN 420, EN 388)

These gloves are designed to protect against the simple mechanical risks caused by abrasion, cutting, tearing and perforation.

Levels of performance for each risk:



TEST	evaluation of performance level					
	0	1	2	3	4	5
A. Endurance against abrasion (cycles)	<100	100	500	2000	600	
B. Endurance against cutting (coefficient)	<1,2	1,2	2,5	5,0	10,0	20,0
C. Endurance against tearing (newton)	<10	10	25	50	75	
D. Endurance against puncture (newton)	<20	20	60	100	150	

#### Maintenance and Storage

Gloves do not require any special maintenance. They can be cleaned with a cloth dampened with mild soapy water. Do not bleach with chlorine. Dry slowly and freely - do not dry on heaters and other heating elements.

Gloves should be stored under normal room conditions (temperature to 20 °C, relative humidity 65%), in dry and clean environment, at least 1 m from heat sources, away from direct solar radiation and away from pests.

Warning: black gloves when wet may release the colour.

Available size range: 07, 08, 09, 10, 11

10/2013



[www.singingrock.com](http://www.singingrock.com)

SINGING ROCK s.r.o.  
Poniklá 317  
CZ - 512 42 Poniklá  
Czech Republic  
Tel. + 420 481 585 007  
Fax + 420 481 540 040  
E-mail: [info@singingrock.cz](mailto:info@singingrock.cz)

# singing rock



## grippy

#### Návod k použití, údržbě a skladování rukavic GRIPPY (EN 420, EN 388)

Tyto rukavice jsou určeny k ochraně proti jednoduchým mechanickým rizikům způsobeným oděrem, proříznutím, roztržením a propíchnutím.

Úrovně provedení pro jednotlivá rizika:



TEST	hodnocení úrovně výkonnosti					
	0	1	2	3	4	5
A. Odolnost proti oděru (cykly)	<100	100	500	2000	600	
B. Odolnost vůči proříznutí (koeficient)	<1,2	1,2	2,5	5,0	10,0	20,0
C. Odolnost proti roztržení (newton)	<10	10	25	50	75	
D. Odolnost vůči propíchnutí (newton)	<20	20	60	100	150	

#### Údržba a skladování

Rukavice nevyžadují žádnou zvláštní údržbu. Je možné je očistit hadrem navlhčeným v jemné mýdlové vodě. Nebělit chlorem. Sušit pomalu a volně - nesušit na přímotopech a jiných topných tělesech. Rukavice se skladují v běžných pokojových podmínkách (teplota do 20 °C, relativní vlhkost vzduchu 65%), v suchém a čistém prostředí, minimálně 1m od topných těles, bez přímého vlivu slunečního záření a z dosahu škůdců.

Upozornění: černé rukavice mohou při navlhčení pouštět barvu.

Dostupný rozsah velikostí: 07; 08; 09; 10; 11